




1 Cut a hole in the ceiling



2 Take DC connector to the power supply



3 Plug the Jump ring and put the panel into the hole



4 Adjust the panels to stick the ceiling tightly

